



Do Buried Utilities Cause Interference with GeoTrax Survey™?

- Aestus can design our survey layouts around known utilities
- Turn cathodic protection off as safeguard
 - Avoid surveying immediately parallel to metallic pipelines



GeoTrax Survey™ Adjacent (Parallel) to Unmarked Metal Pipe

The whole image is very conductive from short circuit. This has only happened to Aestus one time out of hundreds of surveys.



GeoTrax Survey™ (Perpendicular) to Incorrectly Marked Water Line

Note vertical conductive anomaly highlighted in red. Although this vertical conductive zone is essentially "blanked" on our image, the majority of the image on either side of the blanked zone is intact and provides good data.



You Deserve More Certainty IN YOUR SUBSURFACE DATA www.aestusllc.com

info@aestusllc.com

L. 1.888.GEO.TRAX (436.8729)